

Dear User

This document contains important information about updating the firmware for TGF3162 and TGF3082 function / arbitrary / pulse generators from version V1.00 to V1.01 or later. Please read this information very carefully before carrying out the firmware update.

Version 1.01 adds two more calibration steps to calibrate the DAC offset in both channels. These two steps were added to improve the accuracy of the DC offset. This version has no other changes.

Following the update, the instrument would have to be re-calibrated.

If re-calibration is not performed after updating the firmware, then the instrument would perform as before using the current calibration values. However, there will be a message that will pop-up every time the instrument is powered on to inform the user that the instrument is not calibrated.

It is recommended that the instrument be re-calibrated after updating the firmware to version V1.01 or later.

Aim-TTi
Glebe Road
Huntingdon
Cambridgeshire
PE29 7DR
England, U.K.
Tel: 01480 412451
Email: sales@aimtti.com